

YALETOWN PLUMBING SERVICES LTD
1503-1255 Seymour St. Vancouver, BC V6B 0H1 Phone: 604.727.4484 yaletownplumbing.com





HST #837181627

DATE 2015-03-19	TECHNICIAN Darren Mann		JOB/ORDER # 4530	REFERENCE TEXT Client reference		
FIRST NAME Elisabet		LAST NAME Mesropian				
BILLING ADDRESS COMPANY / BILLING NAME 1702 - 1255 SEYMOUR ST VANCOUVER, V6B0H1 BRITISH COLUMBIA, CANADA			1702 - 1255 SEYMOU VANCOUVER, V6B0	SERVICE ADDRESS 1702 - 1255 SEYMOUR ST BUZ#852 VANCOUVER, V6B0H1 BRITISH COLUMBIA, CANADA		
PHONE 778.997.9904			EMAIL elisabet.mesropian@	EMAIL elisabet.mesropian@live.com.ar		

REASON FOR TODAY'S CALL:

-inspection of all plumbing fixtures.

DESCRIPTION OF WORK PERFORMED:

---GUEST BATHROOM: The tub drain was recently replaced. Tub spout diverter, shower head, and shower valve are all in good working order. The toilet supply line is braided stainless and has no signs of wear. The toilet flapper and FillValve are in good condition and toilet is flushing as it should. The lavatory faucet is in good working order and the supply lines are braided stainless with no signs of wear. I filled and drained the lavatory sink; the drain is flowing freely and there is no sign of moisture in the cabinet below. ---MASTER BATHROOM: The tub drain was recently replaced. Tub spout diverter and shower valve are in good working order but the *shower head is broken and should be replaced. The toilet supply line is braided stainless and has no signs of wear. The toilet flapper and FillValve are in good condition and toilet is flushing as it should. The lavatory faucet is in good working order and the supply lines are braided stainless with no signs of wear. I filled and drained the lavatory sink; the drain is flowing freely but I did notice a small amount of water seeping out of threads on the mechanical drain. I sealed this with elec tape and tested again multiple times with no signs of moisture. ---KITCHEN: The kitchen faucet is working as it should, the supply lines are braided stainless and show no signs of wear. I filled the kitchen sink and drained it while running the garburator. The garburator is working as it should and there are no signs of moisture from the drainage. I removed the kick to allow access to the underside of the dishwasher and ran it through a short cycle. The dishwasher supply line is lex and shows no sign of wear, and there is no sign of moisture under the machine. The laundry supply hoses are braided stainless type.

TECHNICIAN RECOMMENDATIONS:

*master shower head

QTY.	CODE	DESCRIPTION			PRICE
1		Labour		\$99.00	\$99.00
		warra	INTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$99.00
			<u>LABOUR</u> - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$4.95
		ls from your	WARRANTY ON CUSTOMER SUPPLIED MATERIALS.		\$103.95
		INTE	INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND		

Thank You!

MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E

