INVOICE
5564
HST #837181627

DATE 2014-04-07	TECHNICIAN Darren Mann	JOB/ORDER # 3194	REFERENCE TEXT Client reference

FIRST NAME Alon	LAST NAME Segev

BILLING ADDRESS COMPANY / BILLING NAME 1625 MANITOBA ST VANCOUVER, V5Y0B8 BRITISH COLUMBIA, CANADA	SERVICE ADDRESS 3104 - 928 HOMER ST BUZ#5281 AARON(TENANT): 778.823.1163 VANCOUVER, BRITISH COLUMBIA, CANADA
PHONE 604.913.9885	EMAIL asegev@sagerllp.com

REASON FOR TODAY'S CALL:
no hot water in guest bathroom lavatory faucet. *Shane will be home: 604.365.8610

DESCRIPTION OF WORK PERFORMED:
The washer inside the Hot shut off valve under the lavatory faucet had come apart and lodged itself in the supply. I removed the rubber washer and replaced the shut off valve, setm, washer, packing, packing nut, and handle. Tested and working as it should.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Repair Angle Stop	$149.00	$149.00

SUBTOTAL:	$149.00
GST (5%):	$7.45
TOTAL:	$156.45

Give us Feedback
Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
Fill in the required details from your invoice and tell us how we did.

Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

_____   2014-04-07

CUSTOMER SIGNATURE   DATE