INVOICE
8323

HST #837181627

DATE	TECHNICIAN	JOB/ORDER #	REFERENCE TEXT
2016-09-16	Darren Mann	6485	Client reference

FIRST NAME	LAST NAME
Anu	Khanna

BILLING ADDRESS	SERVICE ADDRESS
COMPANY / BILLING NAME 2653 POINT GREY RD VANCOUVER, V6K1A4 BRITISH COLUMBIA, CANADA	2653 POINT GREY RD CHERYL(WIFE): 604.786.2632 VANCOUVER, V6K1A4 BRITISH COLUMBIA, CANADA

PHONE	EMAIL
604.306.8503	anu@khanna-law.com

REASON FOR TODAY'S CALL:
Bathroom sink and bathtub not draining we'll need rotorooter and kitchen tap needs tightening?

DESCRIPTION OF WORK PERFORMED:
-I cleaned the tub and lavatory drains using the PowerSpin drain snake. -The kitchen faucet could not be secured any tighter to the counter due to the way it was originally installed. Given the age of the faucet I suggested installing a new faucet over removing and re-installing the existing one with proper cut out wood supports.

TECHNICIAN RECOMMENDATIONS:
*The tub overflow does not have a gasket and is also not fully attached to the drain in behind the tub. I suggested having Dunbar Plumbing(604.312.2686) take a look and see if they know of a way this can be rectified without removal of the tub. *I tested the lavatory drain by filling and draining it multiple times and it is not leaking but the lavatory sink drain stopper could not be re-attached because the connection between the mechanical drain body and the lever arm will leak if moved up or down.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Clean drain using PowerSpin / Tub/Shower	$149.00	$149.00

SUBTOTAL:	$149.00
GST (5%):	$7.45
TOTAL:	$156.45

Give us Feedback

Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
Fill in the required details from your invoice and tell us how we did.

Thank You!

2016-09-16

_____   _____
CUSTOMER SIGNATURE   DATE