



DATE 2018-06-11	TECHNICIAN Darren Mann	JOB/ORDER # 8561	REFERENCE TEXT Client reference
FIRST NAME Ya-Hsun	LAST NAME Lan		
BILLING ADDRESS COMPANY / BILLING NAME 1403 - 1225 RICHARDS ST VANCOUVER , V6Z 2E9 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 1403 - 1225 RICHARDS ST VANCOUVER , V6Z 2E9 BRITISH COLUMBIA, CANADA	
PHONE 604.760.8693		EMAIL yacolourluz@gmail.com	

REASON FOR TODAY'S CALL:
Shower won't turn off.

DESCRIPTION OF WORK PERFORMED:
I replaced the mixing and pressure balance cartridges within the shower valve and tested. During testing I noticed the tub spout was leak at the back towards the wall. I replaced the tub spout with a new Delta pull-down type diverter spout and tested again.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Replace Mixing & Pressure Balance Cartridge - HC44	\$219.00	\$219.00
1		Replace Tub Spout - ADD-ON PRICING	\$79.00	\$79.00
SUBTOTAL:			\$298.00	\$298.00
GST (5%):			\$14.90	\$14.90
TOTAL:			\$312.90	\$312.90

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

2018-06-11

CUSTOMER SIGNATURE

DATE