



DATE 2020-01-02	TECHNICIAN Darren Mann	JOB/ORDER # 9839	REFERENCE TEXT Client reference
FIRST NAME Frank	LAST NAME Hangler		
BILLING ADDRESS COMPANY / BILLING NAME 1007 - 1330 HORNBY ST VANCOUVER, V6Z 1W5 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 1007 - 1330 HORNBY ST, BUZZER 090 VANCOUVER, V6Z 1W5 BRITISH COLUMBIA, CANADA	
PHONE 778.871.9661		EMAIL fhangler@gmail.com	

REASON FOR TODAY'S CALL:
 The overflow drain for my bathtub has become disconnected. There is a 2-3mm gap between the soft rubber drain and the tub itself. Tonight enough water was able to fall into the gap that it came down through the ceiling of our downstairs neighbour.

DESCRIPTION OF WORK PERFORMED:
 I installed a new tub overflow gasket.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Labour	\$109.00	\$109.00
1		Tapered Waste Overflow Gasket	\$10.00	\$10.00
			SUBTOTAL:	\$119.00
			GST (5%):	\$5.95
			TOTAL:	\$124.95

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

2020-01-02

CUSTOMER SIGNATURE

DATE