



DATE 2012-07-26 04:00 pm	TECHNICIAN darren mann	JOB/ORDER # 427	REFERENCE TEXT Client reference
FIRST NAME Abby		LAST NAME Ferris	
BILLING ADDRESS COMPANY / BILLING NAME #1605 - 289 DRAKE ST BUZ#0065 VANCOUVER, V6B5Z5 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS #1605 - 289 DRAKE ST BUZ#0065 VANCOUVER, V6B5Z5 BRITISH COLUMBIA, CANADA	
PHONE 778.389.3865		EMAIL ferrisabby@gmail.com	

REASON FOR TODAY'S CALL:
 -tub/shower diverter not working

DESCRIPTION OF WORK PERFORMED:
 MASTER -replaced tub spout diverter. Replaced pressure balances and mixing cartridge in shower valve.

TECHNICIAN RECOMMENDATIONS:
 -the handle to activate water flow in the guest shower is very stiff. I recommend replacing the cartridges in this shower as well.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1	2395724	GP76851 MXR & PBU SP KIT	\$114.00	\$114.00
1		Tub Spout Diverter	\$25.00	\$25.00
1		Labour	\$99.00	\$99.00

SUBTOTAL:	\$238.00
HST (12%):	\$28.56
TOTAL:	\$266.56

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.



CUSTOMER SIGNATURE

2012-07-26

DATE