



DATE 2014-04-02	TECHNICIAN Darren Mann	JOB/ORDER # 3181	REFERENCE TEXT Client reference
FIRST NAME Heath		LAST NAME Busse	
BILLING ADDRESS COMPANY / BILLING NAME 933 SEYMOUR VANCOUVER, V6B 6L6 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS #415 - 933 SEYMOUR, BUZZER #066 VANCOUVER, V6B 6L6 BRITISH COLUMBIA, CANADA	
PHONE 604 715 2891		EMAIL Heathbusse@hotmail.com	

REASON FOR TODAY'S CALL:
 -showerhandle very stiff, hard to turn.

DESCRIPTION OF WORK PERFORMED:
 -Replaced shower valve cartridge(Price Pfister). -Removed small amount of hair from the underside of the tub drain stopper.

TECHNICIAN RECOMMENDATIONS:
 If the tub drain stopper is not fully sealing it will have to be replaced. Our price for replacing the tub drain trim would be \$139+gst(parts & labour incl)

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Replace Shower Cartridge - Price Pfister	\$179.00	\$179.00

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

SUBTOTAL:	\$179.00
GST (5%):	\$8.95
TOTAL:	\$187.95

_____ 2014-04-02

 CUSTOMER SIGNATURE DATE