



DATE 2016-02-17	TECHNICIAN Darren Mann	JOB/ORDER # 5848	REFERENCE TEXT Client reference
FIRST NAME Wendy		LAST NAME He	
BILLING ADDRESS COMPANY / BILLING NAME 1302 - 989 NELSON ST VANCOUVER, BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 1302 - 989 NELSON ST BUZZER: #141 VANCOUVER, V6Z 2S1 BRITISH COLUMBIA, CANADA	
PHONE 778.869.6328		EMAIL wendyhe0404@gmail.com	

REASON FOR TODAY'S CALL:
 The turn on -turn off tap in the bathtub is faulty and may be leaking


DESCRIPTION OF WORK PERFORMED:
 ----Guest Bathroom: The tub spout was not diverting water to the shower head, I replaced this tub spout. I removed the valve trim and tested the cartridge is showing no signs of leaking. ---Master Bathroom: I removed the valve trim and tested the cartridge is showing no signs of leaking.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Replace Standard Tub Spout Diverter	\$159.00	\$159.00

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY
LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.



_____ 2016-02-17

 CUSTOMER SIGNATURE DATE

SUBTOTAL:	\$159.00
GST (5%):	\$7.95
TOTAL:	\$166.95