



DATE 2016-05-10	TECHNICIAN Darren Mann	JOB/ORDER # 6136	REFERENCE TEXT Client reference
FIRST NAME Set		LAST NAME Narathipphatthara	
BILLING ADDRESS COMPANY / BILLING NAME 161 WEST GEORGIA STREET VANCOUVER, V6B 0K9 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 908 - 161 WEST GEORGIA STREET BUZZER: 5095 VANCOUVER, V6B 0K9 BRITISH COLUMBIA, CANADA	
PHONE 7788964407		EMAIL ikillaman@gmail.com	

REASON FOR TODAY'S CALL:

The shower system might be clogged due to low water pressure; and the tub/shower diverter does not function properly as it cannot divert water from the faucet to the shower head. There also seems to be blue coloured residues, possibly chlorine, fell out of the faucet when the diverter was being adjusted.

DESCRIPTION OF WORK PERFORMED:

-The tub spout diverter was broken. This is common for this building. I replaced the spout with a new Delta pull-down type tub spout diverter.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Replace Standard Tub Spout Diverter	\$159.00	\$159.00
			SUBTOTAL:	\$159.00
			GST (5%):	\$7.95
			TOTAL:	\$166.95

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

2016-05-10

CUSTOMER SIGNATURE

DATE