

2016-06-29

DATE

HST #837181627

DATE 2016-06-29	TECHNICIAN Darren Mann		JOB/ORDER # 6284	REFERENCE TEXT 16-0883
FIRST NAME Advent		LAST NAME Admin		
BILLING ADDRESS ADVENT REAL ESTA #204 - 1168 HAMILTO VANCOUVER, V6B2S BRITISH COLUMBIA,	ON ST S2		SERVICE ADDRESS 1701 - 1255 SEYMO ANASTASIA: 778.84 VANCOUVER, BRITISH COLUMBIA	OUR ST 6.2527
PHONE 604.736.6478			EMAIL andrea@adventvand	couver.com

REASON FOR TODAY'S CALL:

Tub spout diverter not working.

DESCRIPTION OF WORK PERFORMED:

I replaced the tub spout with a new Delta pull-down type diverter spout and tested.								
QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE				
1		Replace Standard Tub Spout Diverter	\$159.00	\$159.00				
Line	us F	eedback warranty: Parts - Subject to Manufacturer's Warranty	SUBTOTAL:	\$159.00				
Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank You!		LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO MAINTENANCE IS NOT DONE ON DEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$7.95				
		INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY WE did. MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, PLETED DETERIOR AT ONLY OF LEAD PURES, CLEAN OUTS AND ANY OTHER DAMAGES.	TOTAL:	\$166.95				

CUSTOMER SIGNATURE