



DATE 2016-10-26	TECHNICIAN Darren Mann	JOB/ORDER # 6650	REFERENCE TEXT Client reference
FIRST NAME Kelly	LAST NAME Kim		
BILLING ADDRESS COMPANY / BILLING NAME 704 - 939 HOMER ST VANCOUVER, V6B 2W6 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 704 - 939 HOMER STREET BUZZER: 0155 VANCOUVER, V6B 2W6 BRITISH COLUMBIA, CANADA	
PHONE 604-771-9849		EMAIL kellyhkim@yahoo.com	

REASON FOR TODAY'S CALL:
 The water dribbled from the bathtub faucet for few week and stop working

DESCRIPTION OF WORK PERFORMED:
 -I repaired the Hot & cold Integral stops in both tub/shower valves by replacing the washers, stems, packing, packing nuts, and handles. I then replaced the pressure & balance cartridges within the tub/shower valves and tested.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Replace Shower Cartridge - Temp II	\$199.00	\$199.00
1		Replace Shower Cartridge - Temp II *ADD-ON PRICING	\$119.00	\$119.00
4		Repair Integral Stop	\$25.00	\$100.00

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY
LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

SUBTOTAL:	\$418.00
GST (5%):	\$20.90
TOTAL:	\$438.90



_____ 2016-10-26
 CUSTOMER SIGNATURE DATE