



DATE 2018-11-20	TECHNICIAN Darren Mann	JOB/ORDER # 9002	REFERENCE TEXT 18-1587
FIRST NAME Advent		LAST NAME Admin	
BILLING ADDRESS ADVENT REAL ESTATE SERVICES LTD. #204 - 1168 HAMILTON ST VANCOUVER, V6B2S2 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 206 - 535 SMITHE ST MATHEW: 604.818.0872 VANCOUVER, BRITISH COLUMBIA, CANADA	
PHONE 604.736.6478		EMAIL andrea@adventvancouver.com	

REASON FOR TODAY'S CALL:

Kitchen Sink: Faucet leaking Dishwasher: has foul odour, please check drain, advise if appliance technician required *buz#1020

DESCRIPTION OF WORK PERFORMED:

-The leak was coming from the bottom of the faucet spout. I removed the spout and tightened a loose integral piece and reinstalled. Tested and no other leaks present. -I believe the smell from the dishwasher is from moisture trapped inside the machine after use. I suggested trying to use the heat dry option to see if that helps. The dishwasher drain is clear.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Discount Labour	\$99.00	\$99.00

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

SUBTOTAL:	\$99.00
GST (5%):	\$4.95
TOTAL:	\$103.95

_____ 2018-11-20
 CUSTOMER SIGNATURE DATE