



DATE 2019-09-05	TECHNICIAN Darren Mann	JOB/ORDER # 9630	REFERENCE TEXT Client reference
FIRST NAME Lia		LAST NAME Loukas	
BILLING ADDRESS COMPANY / BILLING NAME 309 - 1055 RICHARDS ST VANCOUVER , V6B0C2 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 309 - 1055 RICHARDS ST GRETA(TENANT): 604-356-8274 BUZ#8239 VANCOUVER , V6B0C2 BRITISH COLUMBIA, CANADA	
PHONE 604.721.5360		EMAIL Emilyloukas@gmail.com	

REASON FOR TODAY'S CALL:
 Tub shower diverter not working. Tub draining slowly.

DESCRIPTION OF WORK PERFORMED:
 -The tub/shower diverter spool was breaking down internally due to the friction of it being used. I installed a new diverter spool and tested. -I removed the tub drain stopper and found hair directly underneath. I removed this hair and showed the tenant how to detach and reattach the stopper.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Replace Tub/Shower Diverter - Danze(Taju)	\$129.00	\$129.00

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

SUBTOTAL:	\$129.00
GST (5%):	\$6.45
TOTAL:	\$135.45

_____ 2019-09-05
 CUSTOMER SIGNATURE DATE