



**YALETOWN PLUMBING SERVICES LTD**  
 1503-1255 Seymour St. Vancouver, BC V6B 0H1  
 Phone: 604.727.4484 [yaletownplumbing.com](http://yaletownplumbing.com)



**INVOICE**  
 4817

HST #837181627

DATE 2013-10-21	TECHNICIAN Christopher Ryz	JOB/ORDER # 2379	REFERENCE TEXT Client reference
FIRST NAME Janice	LAST NAME Okamura		
BILLING ADDRESS OKAMURA DENTAL 2635 WEST BROADWAY VANCOUVER, V6K2G2 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 3333 WEST 28TH AVE VANCOUVER, V6S1R8 BRITISH COLUMBIA, CANADA	
PHONE 604.616.8827 C		EMAIL janice.okamura@telus.net	

REASON FOR TODAY'S CALL:  
 -tub spout diverter no longer diverting water.

DESCRIPTION OF WORK PERFORMED:  
 Replaced tub spout with new slip on tub spout.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Replace Standard Tub Spout Diverter	\$139.00	\$139.00

**Give us Feedback**  
 Please visit our feedback page at:  
[www.yaletownplumbing.com/feedback](http://www.yaletownplumbing.com/feedback) [1]  
 Fill in the required details from your invoice and tell us how we did.  
**Thank You!**

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

**LABOUR** - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.  
**TERMS:** NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

SUBTOTAL:	\$139.00
GST (5%):	\$6.95
TOTAL:	\$145.95

\_\_\_\_\_ 2013-10-21  
 \_\_\_\_\_  
 CUSTOMER SIGNATURE DATE