



YALETOWN PLUMBING SERVICES LTD
 1503-1255 Seymour St. Vancouver, BC V6B 0H1
 Phone: 604.727.4484 yaletownplumbing.com



INVOICE
5945

HST #837181627

DATE 2014-08-11	TECHNICIAN Darren Mann	JOB/ORDER # 3661	REFERENCE TEXT Client reference
FIRST NAME Neil		LAST NAME Mclver	
BILLING ADDRESS COMPANY / BILLING NAME 1281 SEYMOUR ST VANCOUVER , V6B 0H1 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 1281 SEYMOUR ST VANCOUVER , V6B 0H1 BRITISH COLUMBIA, CANADA	
PHONE 604.340.4002		EMAIL neilmciver@me.com	

REASON FOR TODAY'S CALL:
 -replace tub spout.

DESCRIPTION OF WORK PERFORMED:
 -Replaced tub spout with traditional "pull up" diverter type. -Shower valve handle was loose, I tightened the set screw.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Replace Standard Tub Spout Diverter	\$149.00	\$149.00
			SUBTOTAL:	\$149.00
			GST (5%):	\$7.45
			TOTAL:	\$156.45

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.



 CUSTOMER SIGNATURE

2014-08-11

 DATE