



DATE 2015-02-17	TECHNICIAN Darren Mann	JOB/ORDER # 4459	REFERENCE TEXT
FIRST NAME Mark	LAST NAME Williams		
BILLING ADDRESS CENTURY 21 PRUDENTIAL ESTATES (RMD) LTD 7320 WESTMINSTER HWY RICHMOND, V6X1A1 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 1503 - 1255 SEYMOUR ST JOSIE: 604.349.9940 RICHMOND, BRITISH COLUMBIA, CANADA	
PHONE 604.817.2080		EMAIL mw@century21pel.com	

REASON FOR TODAY'S CALL:  
 -replace tub spout with diverter. -replace tub drain.

DESCRIPTION OF WORK PERFORMED:  
 -replaced the tub spout with a new standard "pull up" type diverter. -replaced the tub drain trim and overflow cap.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Replace Standard Tub Spout Diverter	\$149.00	\$149.00
1		Strata Plan BCS 2756 Discounted Tub Drain Trim Replacement	\$79.00	\$79.00

SUBTOTAL:	\$228.00
GST (5%):	\$11.40
TOTAL:	\$239.40

**Give us Feedback**  
 Please visit our feedback page at:  
[www.yaletownplumbing.com/feedback](http://www.yaletownplumbing.com/feedback) [1]  
 Fill in the required details from your invoice and tell us how we did.  
**Thank You!**

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

**LABOUR** - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.  
**TERMS:** NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

\_\_\_\_\_ 2015-02-17  
 \_\_\_\_\_  
 CUSTOMER SIGNATURE DATE