

DATE 2015-03-20	TECHNICIAN Darren Mann	JOB/ORDER # 4575	REFERENCE TEXT Client reference
FIRST NAME Elizabeth		LAST NAME Dylke	
BILLING ADDRESS COMPANY / BILLING NAME 1225 RICHARDS STREET VANCOUVER , V6B 1E6 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 2001 - 1225 RICHARDS STREET BUZZER: #3001 VANCOUVER , V6B 1E6 BRITISH COLUMBIA, CANADA	
PHONE 604-839-0126		EMAIL elizabeth.dylke@gmail.com	

REASON FOR TODAY'S CALL:

Darin came into fix the faucet in the shower on March 18. The water was not running from the faucet to the shower head. He fixed it but it is now broken again. *call and give

DESCRIPTION OF WORK PERFORMED:

Replaced tub spout in ensuite bathroom with tradition pull-up style.

TECHNICIAN RECOMMENDATIONS:

I informed Elizabeth that even though this style of spout is much sturdier than the previous spout, the diverter should not be pushed down while the shower is activated.

QTY.	CODE	DESCRIPTION
1		Replace Standard Tub Spout Diverter

Give us Feedback

Please visit our feedback page at:

www.yaletownplumbing.com/feedback [1]

Fill in the required details from your invoice and tell us how we did.

Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTE WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROTT SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGE RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.



2015-03-20

CUSTOMER SIGNATURE

DATE