



DATE 2015-07-21	TECHNICIAN Darren Mann	JOB/ORDER # 5048	REFERENCE TEXT
FIRST NAME Jenny	LAST NAME Tsang Lew		
BILLING ADDRESS 1805 - 1483 HOMER ST VANCOUVER, V6Z3C7 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 1805 - 1483 HOMER ST VANCOUVER, V6Z3C7 BRITISH COLUMBIA, CANADA	
PHONE 604.674.5914		EMAIL waterfordconcierge@ranchogroup.com	

REASON FOR TODAY'S CALL:

-Guest bathroom tub spout diverter not working, allowing water to flow through both spout and the shower head. -toilet in the same bathroom running.

DESCRIPTION OF WORK PERFORMED:

-I replaced the toilet Fillvalve, flapper, and supply line. -I removed debris from the tub spout aerator and tested. In good working order.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Replace Toilet Fill-Valve, Flapper, Supply - Standard	\$169.00	\$169.00
SUBTOTAL:				\$169.00
GST (5%):				\$8.45
TOTAL:				\$177.45

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

CUSTOMER SIGNATURE

2015-07-21

DATE