



DATE 2015-09-25	TECHNICIAN Darren Mann	JOB/ORDER # 5302	REFERENCE TEXT Client reference
FIRST NAME Brent		LAST NAME Mudry	
BILLING ADDRESS COMPANY / BILLING NAME 915 WEST 17TH AVE VANCOUVER, V5Z1V5 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 915 WEST 17TH AVE VANCOUVER, BRITISH COLUMBIA, CANADA	
PHONE 604.765.8503		EMAIL bmudry@hotmail.com	

REASON FOR TODAY'S CALL:
 running toilet(Duravit toilet with a Geberit in-wall tank)

DESCRIPTION OF WORK PERFORMED:
 The flushvalve gasket had bubbles in it, I replaced this gasket with new. I also noticed that the fillvalve was installed incorrectly. I removed the fillvalve, re-assembled properly and re-installed. Tested and in good working order.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Replace Flush-Valve Gasket - Geberit In-Wall	\$129.00	\$129.00

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

SUBTOTAL:	\$129.00
GST (5%):	\$6.45
TOTAL:	\$135.45

_____ 2015-09-25
 CUSTOMER SIGNATURE DATE