



DATE 2016-02-15	TECHNICIAN Darren Mann	JOB/ORDER # 5839	REFERENCE TEXT Client reference
FIRST NAME Kirsten		LAST NAME Bell	
BILLING ADDRESS COMPANY / BILLING NAME 1063 BARCLAY ST VANCOUVER, V6E 1G5 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 1063 BARCLAY ST, BUZZER #1063 VANCOUVER, V6E 1G5 BRITISH COLUMBIA, CANADA	
PHONE 778.329.3393		EMAIL artkeb@yahoo.com.au	

REASON FOR TODAY'S CALL:
 -leak under kitchen sink -leak under lavatory sink

DESCRIPTION OF WORK PERFORMED:
 -The kitchen faucet is leaking from the spray head(buttons on top of the head) and finding its way down the spray hose to the underside of the sink. I would say that given the age of the faucet it would make more sense to replace the entire faucet rather than just replacing the spray head. -The leak under the bathroom sink was coming from the lav extensions connected to the lavatory faucet supply lines. I replaced these extensions and tested.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Labour	\$99.00	\$99.00
2		12" Supply Extension	\$10.00	\$20.00

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

2016-02-15

CUSTOMER SIGNATURE

DATE

SUBTOTAL:	\$119.00
GST (5%):	\$5.95
TOTAL:	\$124.95