



HST #837181627

UNIT PRICE

PRICE

DATE 2016-03-24			JOB/O 5975	RDER #	REFERENCE TEXT 16-0394
FIRST NAME Advent		LAST NAME Admin			
BILLING ADDRESS ADVENT REAL ESTATE SERVICES LTD. #204 - 1168 HAMILTON ST VANCOUVER, V6B2S2 BRITISH COLUMBIA, CANADA		4	SERVICE ADDRESS 204 - 1045 HARO ST CHELSIE(NEW TENANT): 1.250.884.1731 VANCOUVER, BRITISH COLUMBIA, CANADA		
PHONE 604.736.6478		EMAIL andrea@adventvancouver.com			

REASON FOR TODAY'S CALL:

Tub/shower diverter broken

QTY.

DESCRIPTION OF WORK PERFORMED:

CODE

---Mar24: I removed the tub faucet handles and trim cover to access the diverter spool. I took pictures of the spool and will track down parts. I am also going to try and find new cartridges and handles as the existing ones are very worn. ---June9: I returned with a new diverter spool, Hot & Cold cartridges, and handles. Installed and tested.

DESCRIPTION

2		Discount Labour		\$99.00	\$198.00
2		139 Cuthbert Handle	3/11/12/	\$13.00	\$26.00
2		CU-1 Cuthbert Cartridge		\$14.00	\$28.00
1		Cuthbert Diverter Spool		\$15.00	\$15.00
Discount delt and for all and a second		SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$267.00	
		LABOUR	LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	GST (5%):	\$13.35
		com/reedback [1]		TOTAL:	\$280.35

Thank You!

invoice and tell us how we did.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY
MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND
MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN,
SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGE
RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK
CHARGES F & O F

2016-03-24 CUSTOMER SIGNATURE