



DATE 2016-11-16	TECHNICIAN Darren Mann	JOB/ORDER # 6704	REFERENCE TEXT Client reference
FIRST NAME Lisa		LAST NAME Chong	
BILLING ADDRESS COMPANY / BILLING NAME 1502 - 1033 MARINASIDE CRES VANCOUVER, V6Z 3A3 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 1502 - 1033 MARINASIDE CRES VANCOUVER, V6Z 3A3 BRITISH COLUMBIA, CANADA	
PHONE 778-888-2574		EMAIL tzyd09@gmail.com	

REASON FOR TODAY'S CALL:
 Bathroom sink leaking - water appears to leaking from the tap connection

DESCRIPTION OF WORK PERFORMED:
 -The lav faucet is leaking from the cartridge. Lisa has decided to replace the faucet, she'll give us a call when she has purchased one. -While onsite Lisa mentioned her tub spout was not fully diverting water to the shower. I replaced the tub spout with a new a Delta pull-down type and tested.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Replace Standard Tub Spout Diverter	\$159.00	\$159.00

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

SUBTOTAL: \$159.00
 GST (5%): \$7.95
 TOTAL: \$166.95



2016-11-16

CUSTOMER SIGNATUREDATE