

(a) @SimplyPlumbing f YaletownPlumbing

HST #837181627

DATE 2017-02-03	TECHNICIAN Darren Mann		JOB/ORDER # 6994		REFERENCE TEXT
FIRST NAME Advent		LAST NAME Admin	7		
BILLING ADDRESS ADVENT REAL ESTATE SERVICES LTD. #204 - 1168 HAMILTON ST VANCOUVER, V6B2S2 BRITISH COLUMBIA, CANADA		4	SERVICE ADDRESS 2008 - 1239 WEST GEORGIA ST, BUZ#158 MARCELA: 604.653.5579 VANCOUVER, BRITISH COLUMBIA, CANADA		
PHONE 604.736.6478				EMAIL andrea@adventvancouver.com	

REASON FOR TODAY'S CALL: shower pressure decreased again.

## DESCRIPTION OF WORK PERFORMED:

I was informed that pressure had decreased again. I removed the shower head and found debris from the building's mains to be clogging up the filter of the head again, I cleaned out this debris and also replaced the tub spout as the diverter was not fully diverting the water.

QTY.	CODE		UNIT PRICE	PRICE	
1		Discount Labour		\$99.00	\$99.00
1		Tub Spout W Diverter		\$30.00	\$30.00
Power Toodle du			Y: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$129.00
Give us Feedback Please visit our feedback page at: <u>www.yaletownplumbing.com/feedback</u> [1] Fill in the required details from your invoice and tell us how we did. <u>Thank Youl</u>			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO		\$6.45
		s from your	WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$135.45
		MATERI SETTLE RESULT TERMS	INTEREST AT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. <u>TERMS</u> : NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.		
			2017-02-03		
			CUSTOMER SIGNATURE DATE		