



DATE 2017-06-16	TECHNICIAN Darren Mann	JOB/ORDER # 7391	REFERENCE TEXT Client reference
FIRST NAME Asha		LAST NAME Prasad	
BILLING ADDRESS COMPANY / BILLING NAME 2502 - 1255 SEYMOUR ST VANCOUVER, V6B0H1 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 2502 - 1255 SEYMOUR ST, BUZZER 948 VANCOUVER, V6B0H1 BRITISH COLUMBIA, CANADA	
PHONE 778.689.0409		EMAIL asha_1671@Hotmail.com	

REASON FOR TODAY'S CALL:  
Shower not working. Faucet lever is broken.

DESCRIPTION OF WORK PERFORMED:  
-I replaced the tub spout with a new Delta pull-down type diverter spout and tested. -I recscured the shower valve handle.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Replace Standard Tub Spout Diverter	\$159.00	\$159.00
SUBTOTAL:				\$159.00
GST (5%):				\$7.95
TOTAL:				\$166.95

**Give us Feedback**  
 Please visit our feedback page at:  
[www.yaletownplumbing.com/feedback](http://www.yaletownplumbing.com/feedback) [1]  
 Fill in the required details from your invoice and tell us how we did.  
**Thank You!**

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

**LABOUR** - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.  
**TERMS:** NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

  
 \_\_\_\_\_  
 CUSTOMER SIGNATURE

2017-06-16  
 \_\_\_\_\_  
 DATE