



DATE 2017-07-14	TECHNICIAN Darren Mann	JOB/ORDER # 7507	REFERENCE TEXT Client reference
FIRST NAME Venus		LAST NAME Chan	
BILLING ADDRESS SUTTON WEST COAST REALTY 302 - 1028 BARCLAY STREET VANCOUVER, V6E0B1 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 302 - 1028 BARCLAY STREET, BUZ#0002 JACO(TENANT): 778.990.2174 VANCOUVER, V6E0B1 BRITISH COLUMBIA, CANADA	
PHONE 604.761.8389		EMAIL venus@sutton.com	

REASON FOR TODAY'S CALL:
 The regulator for the shower and the tap is not working properly so when shower is on, water also drip from the tap in the bathtub

DESCRIPTION OF WORK PERFORMED:
 I replaced the tub/shower diverter spool and tested.

TECHNICIAN RECOMMENDATIONS:
 *during testing I noticed the diverter handle set screw was loose, allowing the handle to slide on the lever that connects to the diverter spool. I was able to resecure this handle but if it comes loose again a new handle may have to be ordered.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Replace Tub/Shower Diverter - Danze(Taju)	\$139.00	\$139.00

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

CUSTOMER SIGNATURE _____ DATE 2017-07-14

SUBTOTAL:	\$139.00
GST (5%):	\$6.95
TOTAL:	\$145.95