



DATE 2017-12-01	TECHNICIAN Darren Mann	JOB/ORDER # 7971	REFERENCE TEXT Client reference
FIRST NAME Rajesh		LAST NAME Suryanarayanan	
BILLING ADDRESS COMPANY / BILLING NAME 1423 - 938 SMITHE ST VANCOUVER, V6Z 3H8 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS APT # 1423 - 938 SMITHE ST, APT # 1423 BUZZER: 2534 VANCOUVER, V6Z 3H8 BRITISH COLUMBIA, CANADA	
PHONE 1.289.208.3216		EMAIL mail2s.rajesh@gmail.com	

REASON FOR TODAY'S CALL:

Wash basin faucet is leaking on the back side even if the tap is slightly open causing water to stagnate on the stone sink. the stone sink is cracking a bit due to this. Also there is some leakage in the closet under the sink.

DESCRIPTION OF WORK PERFORMED:

The faucet was leaking through the cartridge. I replaced the cartridge(K35A) and tested. No other leaks detected.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Replace Lav Faucet Single Lever Cartridge - Standard	\$159.00	\$159.00


Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

SUBTOTAL: \$159.00
 GST (5%): \$7.95
 TOTAL: \$166.95



 CUSTOMER SIGNATURE

2017-12-01

 DATE