



DATE 2018-06-18	TECHNICIAN Darren Mann	JOB/ORDER # 8583	REFERENCE TEXT
FIRST NAME Britta	LAST NAME Love		
BILLING ADDRESS 1809 - 108 WEST CORDOVA ST VANCOUVER, V6B 0G5 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 1809 - 108 WEST CORDOVA ST 7367 VANCOUVER, V6B 0G5 BRITISH COLUMBIA, CANADA	
PHONE 604.899.8891		EMAIL brittablove@yahoo.ca	

REASON FOR TODAY'S CALL:

Hello. Our CAROMA brand toilet is leaking within the tank and needing to fill up every few minutes. The CAROMA toilet is very different under the lid than any I've seen and will need a pro on this brand please. The replacement part number is 75OC17. I suspect a new valve/part is needed. No big rush but would like a quote to get it fixed. Thank you.

DESCRIPTION OF WORK PERFORMED:

I replaced the flushvalve gasket and tested. Toilet seems to be flushing fine with no sign of running.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Replace Toilet FlushValve - Caroma	\$129.00	\$129.00

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

2018-06-18

CUSTOMER SIGNATURE

DATE

SUBTOTAL:	\$129.00
GST (5%):	\$6.45
TOTAL:	\$135.45