



DATE 2018-06-27	TECHNICIAN Darren Mann	JOB/ORDER # 8621	REFERENCE TEXT
FIRST NAME Todd	LAST NAME Liddiard		
BILLING ADDRESS  801 - 1633 ONTARIO ST. VANCOUVER, V5Y 0C2 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS  801 - 1633 ONTARIO ST. VANCOUVER, V5Y 0C2 BRITISH COLUMBIA, CANADA	
PHONE 604.619.3321		EMAIL tliddiard@yahoo.com	

REASON FOR TODAY'S CALL:  
 Water dripping from tank into toilet bowl. Flushing buttons are sticking and catching, not pressing smoothly.

DESCRIPTION OF WORK PERFORMED:  
 I replaced the flushvalve gasket in the guest bathroom toilet and rinsed out the flush buttons and they seem to be in good working order.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Labour	\$109.00	\$109.00
SUBTOTAL:				\$109.00
GST (5%):				\$5.45
TOTAL:				\$114.45

**Give us Feedback**  
 Please visit our feedback page at:  
[www.yaletownplumbing.com/feedback](http://www.yaletownplumbing.com/feedback) [1]  
 Fill in the required details from your invoice and tell us how we did.  
**Thank You!**

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

**LABOUR** - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.  
**TERMS:** NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

\_\_\_\_\_  
 CUSTOMER SIGNATURE

\_\_\_\_\_  
 2018-06-27  
 DATE