



DATE 2018-10-22	TECHNICIAN Darren Mann	JOB/ORDER # 8947	REFERENCE TEXT Client reference
FIRST NAME Gabrielle		LAST NAME Campbell	
BILLING ADDRESS COMPANY / BILLING NAME 2200 - 1280 RICHARDS ST VANCOUVER , V6B 1S2 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 2200 - 1280 RICHARDS ST, BUZZER 00755 VANCOUVER , V6B 1S2 BRITISH COLUMBIA, CANADA	
PHONE 604.762.1368		EMAIL campbell.gabrielle@yahoo.com	

REASON FOR TODAY'S CALL:

The toilet in my guest bathroom is emitting foul odours. This toilet is not used very often and when it is flushed the smell gets worse. Do you have any idea what the problem might be? Gabrielle

DESCRIPTION OF WORK PERFORMED:

I lifted the toilet and found the wax ring to be compromised, allowing sewer gases to seep out into the bathroom. I reset the toilet with a new MaxWax wax ring and braided supply line. Tested and in good working order.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Replace Toilet Wax Seal - Standard	\$189.00	\$189.00
			SUBTOTAL:	\$189.00
			GST (5%):	\$9.45
			TOTAL:	\$198.45

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

2018-10-22

CUSTOMER SIGNATURE

DATE