



DATE 2018-10-24	TECHNICIAN Darren Mann	JOB/ORDER # 8950	REFERENCE TEXT Client reference
FIRST NAME Alice	LAST NAME Jia		
BILLING ADDRESS COMPANY / BILLING NAME 975 BEATTY ST VANCOUVER, V6Z3C5 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 975 BEATTY ST VANCOUVER, V6Z3C5 BRITISH COLUMBIA, CANADA	
PHONE 778.986.7634		EMAIL weiting27@icloud.com	

REASON FOR TODAY'S CALL:
 garbulator is not function, water backflows to the sink. I may need to replace a garbulator, and i am not sure the wire for it has broken or not

DESCRIPTION OF WORK PERFORMED:
 I was able to unjam the garbulator by removing several hard objects from within the grinding chamber. Tested by filling and draining the sink while running the garbulator.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Labour	\$109.00	\$109.00

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

_____ 2018-10-24

 CUSTOMER SIGNATURE DATE

SUBTOTAL:	\$109.00
GST (5%):	\$5.45
TOTAL:	\$114.45