



DATE 2018-11-16	TECHNICIAN Darren Mann	JOB/ORDER # 8996	REFERENCE TEXT Client reference
FIRST NAME Daryoush		LAST NAME Nikzad	
BILLING ADDRESS COMPANY / BILLING NAME 1336 - 1328 WEST PENDER ST VANCOUVER, V6E4T1 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 1905 - 688 ABBOTT ST CHELSEA: 778.678.5625 DANIEL: 1.250.217.0081(DANIEL.R.SLOAN77@GMAIL.COM) VANCOUVER, V6E4T1 BRITISH COLUMBIA, CANADA	
PHONE 604.537.3776 C		EMAIL d_nikzad@hotmail.com	

REASON FOR TODAY'S CALL:
 Garburator drain 90 cracked(Waste King). *call 778.835.6637 for entry.

DESCRIPTION OF WORK PERFORMED:
 The garburator drain 90 was cracked but I also found that the garburator grinding chamber had deteriorated to the point that bits of metal were breaking off. I replaced the garburator with a new Waste King 1001 and tested by filling and draining the sink multiple times while running the garburator.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Supply & Install 1/2HP Waste King 1001 Garburator	\$279.00	\$279.00

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

SUBTOTAL:	\$279.00
GST (5%):	\$13.95
TOTAL:	\$292.95

_____ 2018-11-16
 CUSTOMER SIGNATURE DATE