



DATE 2018-12-20	TECHNICIAN Darren Mann	JOB/ORDER # 9062	REFERENCE TEXT Client reference
FIRST NAME Vera		LAST NAME Sal	
BILLING ADDRESS RENT IT FURNISHED 110 - 1020 MAINLAND STREET VANCOUVER, V6B2T4 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 701 - 1221 BIDWELL AMELIA: 1.819.743.0166 VANCOUVER, BRITISH COLUMBIA, CANADA	
PHONE 778.980.0141		EMAIL PMVan2@rentitfurnished.com	

REASON FOR TODAY'S CALL:
Tub drain stopper stuck in the closed position.

DESCRIPTION OF WORK PERFORMED:
There was hair stuck in the lift/turn mechanism hindering the drain stopper from being able to lift up. I removed the stopper, extracted the hair from within the mechanism, and reinstalled the stopper. Tested and in good working order.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Discount Labour	\$99.00	\$99.00

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

SUBTOTAL:	\$99.00
GST (5%):	\$4.95
TOTAL:	\$103.95

_____ 2018-12-20

 CUSTOMER SIGNATURE DATE