



DATE 2018-12-21	TECHNICIAN Darren Mann	JOB/ORDER # 9059	REFERENCE TEXT Client reference
FIRST NAME Matthew		LAST NAME Thompson	
BILLING ADDRESS COMPANY / BILLING NAME 4 - 2465 WEST 5TH AVE VANCOUVER, V6K 1S7 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 2809 - 928 BEATTY ST VANCOUVER, BRITISH COLUMBIA, CANADA	
PHONE 604-315-2387		EMAIL makaio.thompson@gmail.com	

REASON FOR TODAY'S CALL:
 Bathroom faucet warm water pressure is low. Kitchen faucet does not appear to have the same problem.

DESCRIPTION OF WORK PERFORMED:
 The hot shut off valve under the sink was failing, causing bits of rubber from within the shut off valve to clog up the hot supply line. I repaired this valve by replacing the washer, stem, packing, packing nut, and handle. I then flushed debris out of the supply line and tested.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Repair 1/2" x 3/8" Angle or Straight Stop	\$139.00	\$139.00

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

SUBTOTAL:		\$139.00
GST (5%):		\$6.95
TOTAL:		\$145.95

 <hr/> CUSTOMER SIGNATURE	2018-12-21 <hr/> DATE
--	--------------------------