



DATE 2019-05-09	TECHNICIAN Darren Mann	JOB/ORDER # 9384	REFERENCE TEXT Client reference
FIRST NAME Bang Li		LAST NAME Zhu	
BILLING ADDRESS COMPANY / BILLING NAME 1207 - 1367 ALBERNI ST. VANCOUVER, V6E4R9 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 1207 - 1367 ALBERNI ST (BUZ#0361) JOYCE(TENANT): 778.838.4558 VANCOUVER, V6E4R9 BRITISH COLUMBIA, CANADA	
PHONE 778.869.6667		EMAIL paulblzhu@gmail.com	

REASON FOR TODAY'S CALL:
Garburator jammed.

DESCRIPTION OF WORK PERFORMED:
The garburator grinding chamber had deteriorated to the point that chunks of metal were breaking off. I replaced the garburator with new and tested by filling and draining the sink multiple times while running the garburator.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Supply & Install 1/2HP Badger5 Garburator	\$329.00	\$329.00

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

SUBTOTAL:	\$329.00
GST (5%):	\$16.45
TOTAL:	\$345.45

_____ 2019-05-09
 CUSTOMER SIGNATURE DATE