

HST #837181627

DATE 2019-07-19	TECHNICIAN Darren Mann		JOB/ORDER # 9528		REFERENCE TEXT Client reference
FIRST NAME Sue		LAST NAME Bai	97		
BILLING ADDRESS COMPANY / BILLING NAME 805 - 1318 HOMER ST VANCOUVER, V6B 6A7 BRITISH COLUMBIA, CANADA		19	Ų	SERVICE ADDRESS 805 - 1318 HOMER ST, BUZZI VANCOUVER, V6B 6A7 BRITISH COLUMBIA, CANADA	
PHONE 778.999.2842				EMAIL suebai@hotmail.com	

REASON FOR TODAY'S CALL:

2 slow draining tubs.

DESCRIPTION OF WORK PERFORMED:

-I used the PowerSpin drain snake to remove hair from both tub drains and tested. -The lavatory drains are flowing freely.

QTY.	CODE	DESCRIPTION				PRICE
1	7/	Clean drain using P	owerSpin /	Tub/Shower	\$139.00	\$139.00
<i>Q.</i>	(1	and and	WARRANTY:	ANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$139.00
	Gwe us Feedback ease visit our feedback page at:			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$6.95
www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank Youl		INTEREST A	WARRANTY ON CUSTOMER SUPPLIED MATERIALS. T THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY	TOTAL:	\$145.95	
		MADE THAT MATERIALS SETTLED, RU RESULTING	SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, JSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK			

CUSTOMER SIGNATURE

2019-07-19

DATE