



DATE 2019-09-09	TECHNICIAN Darren Mann	JOB/ORDER # 9638	REFERENCE TEXT Client reference
FIRST NAME Colin		LAST NAME Doig	
BILLING ADDRESS RE/MAX CREST REALTY WESTSIDE 1428 WEST 7TH AVE VANCOUVER, V6H1C1 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 1602 - 833 SEYMOUR ST, BUZ#1125 ROSE: 778.917.5957 VANCOUVER, V6H1C1 BRITISH COLUMBIA, CANADA	
PHONE 604.417.9003		EMAIL colin@colindoig.com	

REASON FOR TODAY'S CALL:
 Clogged bathtub drain. Please let me know if it's due to hair build up.

DESCRIPTION OF WORK PERFORMED:
 I found and removed hair from just under the tub drain stopper. Tested by filling the tub 8? and draining.

TECHNICIAN RECOMMENDATIONS:
 I showed the tenant how to remove the drain stopper so hair can easily be removed if it builds up again in the future.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Discount Labour	\$99.00	\$99.00

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

SUBTOTAL:	\$99.00
GST (5%):	\$4.95
TOTAL:	\$103.95

_____ 2019-09-09

 CUSTOMER SIGNATURE DATE