



DATE 2012-08-30	TECHNICIAN Evan Brandle	JOB/ORDER # 603	REFERENCE TEXT WO#3897
FIRST NAME Andrea		LAST NAME Ferina	
BILLING ADDRESS ADVENT REAL ESTATE SERVICES LTD. #204 - 1168 HAMILTON ST VANCOUVER, V6B2S2 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS #116 - 2780 ACADIA ROAD VANCOUVER, BRITISH COLUMBIA, CANADA	
PHONE 604.736.6478		EMAIL andrea@adventvancouver.com	

REASON FOR TODAY'S CALL:

1 leak under kitchen sink 2 toilet does not flush properly 3 toilet seat pin loose 4 tub drain plug broken (comes off when you try to drain tub)

DESCRIPTION OF WORK PERFORMED:

Disassembled lav drain and re putted and put back together -fixed tub drain stopper -tightened bolts on toilet seat -ran snake through toilet because toilet was leaving toilet paper behind after flushing some times. After auger toilet appears to be fine.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1.5		Discount Labour 89	\$89.00	\$133.50

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

SUBTOTAL:	\$133.50
HST (12%):	\$16.02
TOTAL:	\$149.52

_____ 2012-08-30
 CUSTOMER SIGNATURE DATE