





HST #837181627

DATE 2012-09-25	TECHNICIAN Kristian Evans		JOB/ORDER # 695		REFERENCE TEXT Client reference	
FIRST NAME Jenell		LAST NAME Parsons	97			
BILLING ADDRESS COMPANY / BILLING NAME #404 - 488 HELMCKEN BUZ#0 VANCOUVER, V6B6E4 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS #404 - 488 HELMCKEN BUZ# VANCOUVER, V6B6E4 BRITISH COLUMBIA, CANAL		
PHONE 778.838.8954				EMAIL nellyparsons@gmail.com		

REASON FOR TODAY'S CALL:

-garb jammed. -kitchen sink drainage also seems slow.

DESCRIPTION OF WORK PERFORMED:

Re and re waste king garb. Snake drain line.

QTY.	CODE		UNIT PRICE	PRICE	
1		Labour	\$99.00	\$99.00	
1	0661034	L-1001PC WK Waste Disp 1/2	\$140.00	\$140.00	
Give us Feedback WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY				SUBTOTAL:	\$239.00
Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	HST (12%):	\$28.68
				TOTAL:	\$267.68

Thank You!

invoice and tell us how we did.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E. 2012-09-25 CUSTOMER SIGNATURE