



DATE 2013-01-18	TECHNICIAN Kristian Evans	JOB/ORDER # 1060	REFERENCE TEXT Client reference
FIRST NAME Sophia	LAST NAME Chea		
BILLING ADDRESS VANCOUVER LUXURY REALTY #100 - 1290 HOMER ST VANCOUVER, V6B2Y5 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS #711 - 1238 SEYMOUR ST BUZ#0184 VANCOUVER, BRITISH COLUMBIA, CANADA	
PHONE 604.362.2432		EMAIL sophia@vancouverluxuryrealty.com	

REASON FOR TODAY'S CALL:  
 -garburator not working

DESCRIPTION OF WORK PERFORMED:  
 -Reset garbarator, ran ice and lots of water to flush out. Garb looks to be in good shape. Informed tenent of the reset button below garb.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Labour	\$99.00	\$99.00
SUBTOTAL:				\$99.00
HST (12%):				\$11.88
TOTAL:				\$110.88

**Give us Feedback**  
 Please visit our feedback page at:  
[www.yaletownplumbing.com/feedback](http://www.yaletownplumbing.com/feedback) [1]  
 Fill in the required details from your invoice and tell us how we did.  
**Thank You!**

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

**LABOUR** - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.  
**TERMS:** NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

\_\_\_\_\_ 2013-01-18  
 \_\_\_\_\_  
 CUSTOMER SIGNATURE DATE