

DATE 2013-07-29	TECHNICIAN Darren Mann	JOB/ORDER # 1974	REFERENCE TEXT Client reference
FIRST NAME Genevieve	LAST NAME LeBaron		
BILLING ADDRESS COMPANY / BILLING NAME #603 1275 HAMILTON ST BUZ#68 VANCOUVER, V6B1E2 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 603 - 1275 HAMILTON ST. BUZZER: 68 VANCOUVER, V6B1E2 BRITISH COLUMBIA, CANADA	
PHONE 604.366.3634	EMAIL gclebaron@gmail.com		

REASON FOR TODAY'S CALL:

"The garbage disposal has stopped working. It simply hums, but nothing spins. Sometimes the power doesn't come through at all and it is just dead. We have used the reset button on the bottom. We have cleaned out all food, etc."

DESCRIPTION OF WORK PERFORMED:

-garburator was cracked and leaking. I replaced the garburator with a new Badger5.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Supply & Install 1/2HP Badger5 Garburator	\$299.00	\$299.00

Give us Feedback

Please visit our feedback page at:

www.yaletownplumbing.com/feedback [1]

Fill in the required details from your invoice and tell us how we did.

Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.



2013-07-29

CUSTOMER SIGNATURE

DATE

SUBTOTAL:	\$299.00
GST (5%):	\$14.95
TOTAL:	\$313.95