

(B) @SimplyPlumbing | | YaletownPlumbing



SUBTOTAL: \$0.00

\$0.00

TOTAL:

HST #837181627

DATE 2013-12-04	TECHNICIAN Darren Mann		JOB/ORDER # 2617		REFERENCE TEXT WO#6005		
FIRST NAME Advent		LAST NAME Admin	97				
BILLING ADDRESS ADVENT REAL ESTATE SERVICES LTD. #204 - 1168 HAMILTON ST VANCOUVER, V6B2S2 BRITISH COLUMBIA, CANADA		14	SERVICE ADDRESS 803 - 58 KEEFER PLACE VALERIE(TENANT): 604.352.3150 VANCOUVER, BRITISH COLUMBIA, CANADA				
PHONE 604.736.6478				EMAIL andrea@adventvancouver.com			

REASON FOR TODAY'S CALL:

-issue with heating, always on. (we replaced the zone valve within the past year) -figure out how to remove light cover. ---permission to enter granted. keys ready for pickup at Advent.

DESCRIPTION OF WORK PERFORMED:

-one of the screws holding the zone valve motor in place had come loose. i re-secured the zone valve motor and tested. -sent video of me removing the cover of

Gwe us Feedback Please visit our feedback page at: www.yaletownplumbing.com/feedback [1]	WARRANTY:	PARTS - SUBJECT TO MANUFACTURER'S WARRANTY LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYR WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	
Fill in the required details from your invoice and tell us how we did. Thank You!	MADE THAT MATERIALS SETTLED, RI RESULTING	T THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNT. SERVICES LISTED ABOVE ARE SATISFACTORY COMPLET. LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS USTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLE FROM CLEANING OR REPAIRING EXISTING FIXTURES OR CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR. & O. E.	ED AND THAT CHARGES AND S NOT RESPONSIBLE FOR BROKEN, AN OUTS AND ANY OTHER DAMAGES PIPING.
	<u> </u>		2013-12-04
		CUSTOMER SIGNATURE	DATE