



DATE 2014-04-24	TECHNICIAN Darren Mann	JOB/ORDER # 3243	REFERENCE TEXT Client reference
FIRST NAME John		LAST NAME Wallace	
BILLING ADDRESS COMPANY / BILLING NAME 1625 HORNBY ST VANCOUVER, BRITISH COLUMBIA, CANADA		SERVICE ADDRESS #903 - 1625 HORNBY ST, BUZZER WALLACE VANCOUVER, BRITISH COLUMBIA, CANADA	
PHONE 604.568.7243		EMAIL jcwallace@btinternet.com	

REASON FOR TODAY'S CALL:
 -toilet leaks from the connection between the water supply and the fill valve.

DESCRIPTION OF WORK PERFORMED:
 Replaced the toilet tank to bowl gasket, tank bolts, and supply line.

TECHNICIAN RECOMMENDATIONS:
 If in the future the flush valve gasket requires replacement it will need to be of the Crane type. A universal fill-valve will work.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Replace Tank To Bowl Gasket - Standard	\$169.00	\$169.00
			SUBTOTAL:	\$169.00
			GST (5%):	\$8.45
			TOTAL:	\$177.45

Give us Feedback

Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.

Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

Z C Wallace

2014-04-24

CUSTOMER SIGNATURE

DATE