

DATE 2014-12-23	TECHNICIAN Darren Mann	JOB/ORDER # 4206	REFERENCE TEXT Client reference
FIRST NAME Lionel		LAST NAME Co Ling	
BILLING ADDRESS COMPANY / BILLING NAME 833 SEYMOUR ST. VANCOUVER, V6B 0G4 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 2812 - 833 SEYMOUR ST. VANCOUVER, V6B 0G4 BRITISH COLUMBIA, CANADA	
PHONE 778-855-2877		EMAIL llco79@hotmail.com	

REASON FOR TODAY'S CALL:

Our bath tub is not draining very well. This has happened before and we called you guys last time to clear it. Back then, there was just lots of hair in there. We suspect it's a similar problem this time around.

DESCRIPTION OF WORK PERFORMED:

Used the PowerSpin drain snake to clear a large clump of hair from the tub drain. Tested by filling the tub 6" and draining.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Clean drain using PowerSpin / Tub/Shower	\$139.00	\$139.00

Give us Feedback

Please visit our feedback page at:

www.yaletownplumbing.com/feedback [1]

Fill in the required details from your invoice and tell us how we did.

Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.



2014-12-23

CUSTOMER SIGNATURE

DATE

SUBTOTAL:	\$139.00
GST (5%):	\$6.95
TOTAL:	\$145.95