



DATE 2015-05-14	TECHNICIAN Darren Mann	JOB/ORDER # 4802	REFERENCE TEXT Client reference
FIRST NAME Johanne		LAST NAME Mongrain	
BILLING ADDRESS COMPANY / BILLING NAME 628 KINGHORNE MEWS VANCOUVER, V6Z3H6 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 201 - 628 KINGHORNE MEWS BUZZER: WEARY VANCOUVER, V6Z3H6 BRITISH COLUMBIA, CANADA	
PHONE 6043283175		EMAIL jomongrain@gmail.com	

REASON FOR TODAY'S CALL:
 "Lost pressure in Grohe kitchen tap. Checked sprayer. Picture shows maximum flow."


DESCRIPTION OF WORK PERFORMED:
 The Grohe pushfit style connection between the spray hose and the faucet was gunked up with debris and could not be cleaned out. I had a spare fitting in my van from another faucet. I installed the fitting and tested.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Labour	\$99.00	\$99.00

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY
LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.



 CUSTOMER SIGNATURE

2015-05-14

 DATE

SUBTOTAL:	\$99.00
GST (5%):	\$4.95
TOTAL:	\$103.95