



DATE 2015-06-12	TECHNICIAN Darren Mann	JOB/ORDER # 4909	REFERENCE TEXT Client reference
FIRST NAME Brenda (Lanna)		LAST NAME Olson	
BILLING ADDRESS COMPANY / BILLING NAME 304 - 2015 TRAFALGAR STREET VANCOUVER, V6K 3S5 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 304 - 2015 TRAFALGAR STREET BUZZER: CALL OR TEXT PRIMARY CELL VANCOUVER, V6K 3S5 BRITISH COLUMBIA, CANADA	
PHONE 1.306.209.0999		EMAIL Bren5555@gmail.com	

REASON FOR TODAY'S CALL:
Garburator has quit working

DESCRIPTION OF WORK PERFORMED:
I unjammed the garburator and tested by filling and draining the sink while running the garburator. There didn't seem to be anything out of the ordinary inside the grinding chamber, just a buildup of rust.

TECHNICIAN RECOMMENDATIONS:
The grinding chamber is deteriorating to the point where flakes of rust are breaking off and causing the garburator to seize up. The garburator is now functional but it should be replaced soon.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Labour	\$99.00	\$99.00
			SUBTOTAL:	\$99.00
			GST (5%):	\$4.95
			TOTAL:	\$103.95

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY
LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.



 CUSTOMER SIGNATURE

2015-06-12

 DATE