





HST #837181627

DATE 2015-06-16	TECHNICIAN Darren Mann		JOB/ORDER # 4926		REFERENCE TEXT Client reference
FIRST NAME Joel		LAST NAME Kobylka	9/		
BILLING ADDRESS COMPANY / BILLING NAME 1265 WEST 11TH AVENUE VANCOUVER, V6H 1K6 BRITISH COLUMBIA, CANADA				SERVICE ADDRESS  106 - 1265 WEST 11TH AVENUBUZZER: CALL CELL VANCOUVER, V6H 1K6 BRITISH COLUMBIA, CANADA	-
PHONE 6046904949				EMAIL joelkobylka@gmail.com	

REASON FOR TODAY'S CALL:

water leaking from hose-bib vacuum breaker.

DESCRIPTION OF WORK PERFORMED:

Replaced hose bib vacuum breaker.

QTY.	CODE		DESCRIPTION	UNIT PRICE	PRICE	
1	//	Repair Hose-Bib Vacuu	Repair Hose-Bib Vacuum Breaker			
		eodhach war	REANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$109.00	
			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$5.45	
			WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$114.45	
		IN	ITEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY ADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND			

<u> Thank You!</u>

MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

2015-06-16

CUSTOMER SIGNATURE

DATE