



HST #837181627

	TECHNICIAN Darren Mann		JOB/ORDER # 4963	REFERENCE TEXT Client reference	
FIRST NAME Meriel		LAST NAME Lindley			
BILLING ADDRESS COMPANY / BILLING NAME 1003 BURNABY STREET VANCOUVER, V6E 4R7 BRITISH COLUMBIA, CANADA			SERVICE ADDRES  1807 - 1003 BURNA BUZZER: 4024 VANCOUVER, V6E BRITISH COLUMBI	ABY STREET 4R7	
PHONE 604 605 0585			EMAIL merlind56@gmail.co	om	

## REASON FOR TODAY'S CALL:

"flapper broke; tried to replace but not quite sealed, so it still leaks. Would like to replace flappers on both toilets as the other one is old."

## DESCRIPTION OF WORK PERFORMED:

I replaced the toilet flapper in the second floor bathroom.(I only had the one flapper in my van stock)

QTY.	CODE	DESCRIPTION		UNIT PRICE	PRICE
1	1	Labour		\$99.00	\$99.00
1	2390309	GP1078440		\$16.00	\$16.00
WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY			SUBTOTAL:	\$115.00	
Please visit our feedback page at:  www.yaletownplumbing.com/feedback [1]  Fill in the required details from your			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	GST (5%):	\$5.75
		s from your		TOTAL:	\$120.75

<u> Thank You!</u>

invoice and tell us how we did.

MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.  $\underline{\textbf{TERMS}}\text{: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK}$ CHARGES, E. & O. E.

CUSTOMER SIGNATURE

2015-06-26