



DATE 2015-07-02	TECHNICIAN Darren Mann	JOB/ORDER # 4983	REFERENCE TEXT Client reference
FIRST NAME Kathy		LAST NAME Gallagher	
BILLING ADDRESS COMPANY / BILLING NAME #2701 - 1500 HORNBY ST BUZ#3132 VANCOUVER, V6Z-2R1 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS #2701 - 1500 HORNBY ST BUZ#3132 VANCOUVER, V6Z-2R1 BRITISH COLUMBIA, CANADA	
PHONE 604.683.1488		EMAIL kmikegallagher@aol.com	

REASON FOR TODAY'S CALL:
leak under guest bathroom lavatory sink when air conditioner is on

DESCRIPTION OF WORK PERFORMED:
There was a leak coming from the ABS drain leading from the a/c unit. the leak was coming from the 45 where it comes out of the wall under the guest bathroom lavatory sink. i used ABS glue to seal this leak and secured a small tupperware container to the cabinet wall under this fitting in the case that a small drip re-developes in the future to mitigate any further water damage to the cabinet below.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Labour	\$99.00	\$99.00
			SUBTOTAL:	\$99.00
			GST (5%):	\$4.95
			TOTAL:	\$103.95

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY
LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

2015-07-02

 CUSTOMER SIGNATURE

 DATE