



DATE 2015-07-13	TECHNICIAN Darren Mann	JOB/ORDER # 5015	REFERENCE TEXT Client reference
FIRST NAME Margaret		LAST NAME Segal	
BILLING ADDRESS COMPANY / BILLING NAME #3101 - 1483 ST HOMER BUZ#1170 VANCOUVER, V6Z3C7 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS #3101 - 1483 ST HOMER BUZ#1170 VANCOUVER, V6Z3C7 BRITISH COLUMBIA, CANADA	
PHONE 604.733.8838		EMAIL margseg@shaw.ca	

REASON FOR TODAY'S CALL:
toilet seems to be rusting inside tank


DESCRIPTION OF WORK PERFORMED:
I replaced the fillvalve & supply line in the guest bathroom toilet(American Standard, original to building) and cleaned the inside of the toilet tank.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Replace toilet FillValve - standard	\$149.00	\$149.00
SUBTOTAL:			\$149.00	\$149.00
GST (5%):			\$7.45	\$7.45
TOTAL:			\$156.45	\$156.45

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY
LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.



 CUSTOMER SIGNATURE

2015-07-13

 DATE