



DATE 2015-07-15	TECHNICIAN Darren Mann	JOB/ORDER # 5026	REFERENCE TEXT Client reference
FIRST NAME Mahmoud		LAST NAME Jedi	
BILLING ADDRESS COMPANY / BILLING NAME 2302 - 1367 ALBERNI ST VANCOUVER, V6E4R9 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 2302 - 1367 ALBERNI ST, BUZZER 0441 VANCOUVER, V6E4R9 BRITISH COLUMBIA, CANADA	
PHONE 604.734.8580		EMAIL mahmoud.jedi@yahoo.com	

REASON FOR TODAY'S CALL:
garburator not working

DESCRIPTION OF WORK PERFORMED:
The garburator grinding chamber had rusted out and was unfixable. I replaced the garburator with a new Waste King 1001 and tested by filling and draining the sink while running the garburator.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Supply & Install 1/2HP Waste King 1001 Garburator	\$279.00	\$279.00

SUBTOTAL:	\$279.00
GST (5%):	\$13.95
TOTAL:	\$292.95

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

2015-07-15

CUSTOMER SIGNATURE

DATE